JAN 17 7006 W

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

Fre application of: Prindiville, et al.

Date Mailed January 13, 2006

Patent No. 6,858,927 62

Issued: February 22, 2005 **Application No.** 09/971,952

Filed: October 4, 2001 Confirmation No. 4096

For: SEMICONDUCTOR PACKAGES AND

METHODS FOR MAKING THE SAME

Examiner: David A. Zarneke

JAN 2 0 2006

Certificate

Art Unit: 2827

of Correction

Attorney Reference No. 6047-61248-01

COMMISSIONER FOR PATENTS P.O. BOX 1450 ALEXANDRIA, VA 22313-1450

REQUEST FOR CERTIFICATE OF CORRECTION

The following errors were noted in the printed patent:

In the Abstract:

Line 8, "pressure sensitive" should be --pressure-sensitive-- (application page 23, lines 9-10).

In the Specification:

Column 3, line 29, "(FIG. 2a and 2B)" should be --(FIGS. 2A and 2B)-- (application, page 5, line 9).

Column 5, line 35, "opening (see" should be --opening, see-- (application, page 8, line 24).

Column 6, line 4, "defect substrates" should be --defective substrates-- (application, page 9, line 24).

Column 6, line 5, "sites are" should be --sites) are-- (application, page 9, line 25).

01/18/2006 HVUDNG1 00000027 6858927

Column 6, lines 10-11, "defect substrates" should be --defective substrates-- (application page 9, line 29).

Column 8, line 12, "includes" should be --include-- (application, page 13, line 11).

In the Claims:

Claim 11 (Column 9, lines 3-4), "one indidual defective substrate, wherein the defective pattern of conductors" should be --one individual defective substrate, wherein the defective substrate has a defective pattern of conductors-- (Claim 43, Amendment of May 21, 2004, pages 4-5).

A Certificate of Correction is enclosed to make formal notice of the errors in the referenced patent. Our check in the amount of \$100 is enclosed.

Please return the enclosed postcard to confirm that these documents have been received.

Respectfully submitted,

KLARQUIST SPARKMAN, LLP

Ву

Donald L. Stephens Jr.

Registration No. 34,022

One World Trade Center, Suite 1600

121 S.W. Salmon Street

Portland, Oregon 97204 Telephone: (503) 226-7391

Facsimile: (503) 228-9446

cc: Client

Docketing

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO. : 6,858,927 62

DATED : February 22, 2005

INVENTOR(S) : Prindiville, et al.

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Line 8 of the Abstract

Line 8, "pressure sensitive" should be --pressure-sensitive--.

Column 3,

12.1 . 4

Line 29, "(FIG. 2a and 2B)" should be --(FIGS. 2A and 2B)--.

Column 5,

Line 35, "opening (see" should be --opening, see--.

Column 6,

Line 4, "defect substrates" should be --defective substrates--.

Line 5, "sites are" should be --sites) are--.

Lines 10-11, "defect substrates" should be --defective substrates--.

Column 8,

Line 12, "includes" should be --include--.

Column 9.

Lines 3-4, "one indidual defective substrate, wherein the defective pattern of conductors" should be --one individual defective substrate, wherein the defective substrate has a defective pattern of conductors--.